

POTTORFF®

Title: **Powder Coat / Wet Coat Painter**
Reports to: Production Supervisor
Location: Fort Worth, TX 76106

Job Summary: Prepare and paint aluminum louvers, sunshades, and other architectural products in a production environment. Perform all aspects of chemical resistance coatings application per customer and company specifications. Read and understand Manufactures Technical Data Sheets for mixing, applying and curing paints. Meet internal and external customer needs by making continuous improvements and attaining departmental goals/objectives.

Equipment Used: Paint gun, Pressure Pot, Agitator, orbital sander, Computer, Color Sampling Equipment, pallet jack, and various painting tools necessary to perform duties.

Education / Experience Requirement

- Minimum 2 years experience painting aluminum materials.
- Experience with metallics and irregular shapes.
- Must be reliable and willing to work overtime when required.

Specific Skills Required

- Maintain, set-up, and use multiple types of spray equipment.
- Ensure on-time delivery and quality of painted product.
- Read and interpret drawings/prints and be familiar with the basic types of industrial spray applications and equipment.
- Verify parts to paint chips.
- Document the application process as required by customer and company requirements.
- Perform self-inspection of painted items and maintain a high standard of quality.
- Recommend/implement process improvements.
- Maintain excellent housekeeping in and around the working area.
- Maintain VOC and Air Permit compliance logging
- Assist other painters and paint support team members in completion of tasks.
- Perform other duties as required.

Other Duties and Responsibilities: This position will at times not paint. During those times this individual will serve as a material handler for other painters and at times will work on the assembly line when there is a lack of paint work.

Physical Demands

- At times be able to work longer than normal hours and be able to lift 50lbs.
- Appearance: Must be clean shaven in order to wear 3M Full Face Respirator.
- Must be able to physically work while wearing Full Face Respirator. Must undergo Medical Surveillance, PFT (Pulmonary Function Testing), annually.